

Product Description



Product Name	Musical can
Your reference number	Client no. XX
P/O number	ODM sz 5245
Quantity	1200
Supplier	**** industrial ltd.
Inspection date	March 15 th , 03
Inspection location	Shenzhen, China
Inspector	Pierre-Yves GRAMOND
Supervisor	Conor O'Donovan

RESULT

FAILED

Inspection Standards

Inspection type	Final Random Inspection
Sampling standard	MIL-STD-105E
Sampling level	SINGLE LEVEL II
AQL for Critical defective	0
AQL for Major defective	2.5
AQL for Minor defective	4
Sample size for Cri/Maj/Min	80/80/80
Total number of cartons	600
Number of inspected cartons	40



Inspector's picture




Supervisor's picture



Map



Gate of factory



Office



Production line

Your special requirement

Carton drop test from 61 cms height, drop 10 times, at 1 corner, 3 edges and 6 faces



Performed on 2 export cartons, found the result was OK.

Function test according to instruction manual



Performed on all samples, found the result were OK

Plug the Can during 4 hours functioning



Performed on 13 samples (S 3) , found the result were OK

Defectives List

	Defectives Description	CRI	MAJ	MIN
Within AQL	Cd door touch open can catch and be difficult to open	0	5	0

Picture



	Scratches on can	0	0	8
--	------------------	---	---	---



	Glue mark on speaker	0	0	3
--	----------------------	---	---	---



Number of defectives	0	5	11
Maximum Allowed	0	5	7
No. of inspected samples	80	80	80

Remark

The web site directory [www. sanmiguel.sp](http://www.sanmiguel.sp) on the front of the Can is not written corectly, as you can see on the picture below. We can read [saimiguel.sp](http://www.saimiguel.sp) instead of [sanmiguel.sp](http://www.sanmiguel.sp) This mistake can't be include in the AQL defect because it concern all the mass production. Only you can take a decision about this defect.

No reference sample for comparing during inspection time.

The instructions are written only in English.

Production is now 95% complete. Factory to finish production within 2 days.

Packin g

Unit packing

each piece was packed in a polybag



Inner packing

each piece was packed in an individual white box with protection



Outer packing

two white box / export carton


66.5*34*56cm



Production Pictures

Shipping Mark

Front mark



Side Mark



Your Product



Remote control




Product Top with CD door open

Other Pictures



CE logo on can



Instruction only in English



Mistake on web site directory

Cartons



Total cartons number 1



Inspected cartons



Total cartons number 2